MITSUBISHI MOTOR SALES OF AMERICA, Inc.

TECHNICAL SERVICE BULLETIN

SUBJECT:

Service Bulletin Listing

NO.

DATE

MODEL Montero

SERVICE CAMPAIGN	
	MMSA SC-90-003 - 1989 V6 Montero Throttle Heater Kit Insta.pdf
SAFETY RECALL	
	MMSA SR-01-002 - Loose Crankshaft Pulley Bolt (SAFETY RECA.pdf
	MMSA SR-95-002 - Front Seatbelt Buckle Safety Recall.pdf
TECHNICAL SERVICE BULLETIN	
	MMSA TSB-88-23-010 - 1988 Truck Side Window Spacer.pdf
	MMSA TSB-88-25-001 - 1989 Trucks and Monteros High Altitud.pdf
	MMSA TSB-89-00-001 - 1989 VIN Decoder.pdf
	MMSA TSB-89-00-001 - New TSB Service Groups.pdf
	MMSA TSB-89-03-001 - LSD Case Measurements (SMR).pdf
	MMSA TSB-89-11-007 - Engine Oil Pump Measurement Update.pdf
	MMSA TSB-89-12-001 - Montero V6 Oil Capacity (SMR).pdf
	MMSA TSB-89-14-001 - Throttle Heater Installation on 1989 .pdf
	MMSA TSB-89-16-001 - MPI Circuit (SMR).pdf
	MMSA TSB-89-16-003 - MPI Circuit Diagnosis (SMR).pdf
	MMSA TSB-89-16-004 - Ignition Timing Adjustment on 4G61, 4.pdf
	MMSA TSB-89-16-007 - 1989 I4 Montero Distributor (SMR).pdf
	MMSA TSB-89-17-001 - Rear Suspension Bushing Change on 198.pdf
	MMSA TSB-89-21-002 - Valve Body Changes in KM170 Series Tr.pdf
	MMSA TSB-89-21-005 - Montero ATF Warning Light Specificati.pdf
	MMSA TSB-89-23-006 - 1989 Exterior Colors Codes and Applic.pdf
	MMSA TSB-89-27-001 - Lock Washer on RWD Axles.pdf
	MMSA TSB-89-27-002 - 89 Montero Rear Differential Tool (SM.pdf
	MMSA TSB-89-31-001 - Montero Spare Wheel Lock Location.pdf
	MMSA TSB-89-55-001 - Montero Rear AC (SMR).pdf
	MMSA TSB-90-00-007 - Power Door Lock Interface Module Conn.pdf
	MMSA TSB-90-13-003 - 1989 V6 Montero Throttle Body Removal.pdf
	MMSA TSB-90-22-002 - 89 Montero MT Speacial Tools (SMR).pdf
	MMSA TSB-90-23-011 - Overdrive Shift Switch Removal (SMR).pdf
	MMSA TSB-90-27-004 - LSD Shudder.pdf
	MMSA TSB-90-42B-001 - Windshield Installation.pdf
	MMSA TSB-90-42B-002 - Body Water Leak Diagnosis and Repair.pdf
	MMSA TSB-91-00-003 - Adding Friction Modifier to MT Case (.pdf
	MMSA TSB-91-00-005 - Montero Engine Oil Capacity (SMR).pdf
	MMSA TSB-91-11-001 - V6 Crankshaft Bearing Size (SMR).pdf
	MMSA TSB-91-11-010 - Piston Pin Installation Tool Instruct.pdf
	MMSA TSB-91-13-004 - Oxygen Sensor Check.pdf
	MMSA TSB-91-17-002 - No Problem Found Parts (California Mo.pdf
	MMSA TSB-91-17-003 - Vehicle Emissions Control Information.pdf
	MMSA TSB-91-22-008 - V5MT1 5spd MT Hard Shift.pdf
	MMSA TSB-91-23-006 - AT Hydraulic Circuit (SMR).pdf
	MMSA TSB-91-27-004 - Axle Drive Pinion Tool (SMR).pdf
	MMSA TSB-92-00-003 - ECU Circuit Testing Precautions.pdf
	MMSA TSB-92-00-005 - VIN Master Decoder.pdf
	MMSA TSB-92-11-003 - Cylinder Head Bolt Tightening Torque .pdf
	MMSA TSB-92-31-001 - Wheel Lug Nut Torque.pdf
	MMSA TSB-92-35-003 - Brake Pad Installation Service Points.pdf
	MMSA TSB-92-35-008 - Brake Rotor Servicing.pdf

FILE UNDER:

CIRCULATE TO:

- ☐ GENERAL MANAGER
- ☐ PARTS MANAGER
- ☑ TECHNICIAN
- ☐ SERVICE ADVISOR
- ☐ SERVICE MANAGER
- ☐ WARRANTY PROCESSOR
- ☐ SALES MANAGER

MITSUBISHI MOTOR SALES OF AMERICA, Inc.

TECHNICAL SERVICE BULLETIN

SUBJECT:

Service Bulletin Listing

NO.

DATE

MODEL Montero

TECHNICAL SERVICE BULLETIN (Continued)
MMSA TSB-92-51-001 - Paint Damage Identification and Repai.pdf
MMSA TSB-93-00-008 - Revised Automotive Terms.pdf
MMSA TSB-93-21-001 - Flywheel Resurfacing and Replacement.pdf
MMSA TSB-93-22-001 - MT Transaxle Gear Oil.pdf
MMSA TSB-93-23-005 - 89-90 Montero Non-Lockup AT Component.pdf
MMSA TSB-93-54-003 - Horn Adjustment.pdf
MMSA TSB-93-55-001 - AC Odor.pdf
MMSA TSB-94-55-001 - AC System Leak Check.pdf
MMSA TSB-95-11-001 - Valve Noise at Start-Up.pdf
MMSA TSB-95-16-003 - Spark Plug Fouling.pdf
MMSA TSB-95-54-001 - Rear Window Defogger Grid Repair.pdf
MMSA TSB-96-11-003 - Engine Block Heater Application and I.pdf
MMSA TSB-96-11-005 - Oil Economy Test.pdf
MMSA TSB-96-42A-007 - Window Fogging.pdf
NATIONAL HIGHWAY TRANSPORTATION ADMINISTRATION
NHTSA RC-89V027-NN - 89 Raider Throttle Icing Recall.pdf
NHTSA RC-89V030-NN - 89 Montero Throttle Icing Recall.pdf
NHTSA RC-93E023-NN - 89 Raider Reese Hitch Recall.pdf
NHTSA RC-95V103-NN - 1995 Seatbelt Recall.pdf

FILE UNDER:

CIRCULATE TO:

- ☐ GENERAL MANAGER
- ☐ PARTS MANAGER
- ☑ TECHNICIAN
- ☐ SERVICE ADVISOR
- ☐ SERVICE MANAGER
- ☐ WARRANTY PROCESSOR
- ☐ SALES MANAGER